

RI 9568

REPORT OF INVESTIGATIONS/1995

Human Factors Analysis of Roof Bolting Hazards in Underground Coal Mines

UNITED STATES DEPARTMENT OF THE INTERIOR



UNITED STATES BUREAU OF MINES



U.S. Department of the Interior
Mission Statement

As the Nation's principal conservation agency, the Department of the Interior has responsibility for most of our nationally-owned public lands and natural resources. This includes fostering sound use of our land and water resources; protecting our fish, wildlife, and biological diversity; preserving the environmental and cultural values of our national parks and historical places; and providing for the enjoyment of life through outdoor recreation. The Department assesses our energy and mineral resources and works to ensure that their development is in the best interests of all our people by encouraging stewardship and citizen participation in their care. The Department also has a major responsibility for American Indian reservation communities and for people who live in island territories under U.S. administration.

Report of Investigations 9568

Human Factors Analysis of Roof Bolting Hazards in Underground Coal Mines

By Fred C. Turin and others

UNITED STATES DEPARTMENT OF THE INTERIOR
Bruce Babbitt, Secretary

BUREAU OF MINES
Rhea Lydia Graham, Director

International Standard Serial Number
ISSN 1066-5552

CONTENTS

	<i>Page</i>
Abstract	1
Introduction	2
Method	2
Accident database analyses	2
Mine visits and interviews	3
Manufacturer contacts	3
Interviews with injured operators	3
Review of past research	3
Ranking of hazard-reduction recommendations	3
Results	4
Accident data analyses results	4
Mine visit and interview results	4
Accidental actuation of controls	4
Bolters getting into pinch points	5
Use of fast-feed lever	5
Comparison of old and new Roof Ranger boom designs	5
Comparison of one- and two-handed fast-feed designs	5
Manufacturer contact results	5
Injured operator interview summaries	6
Review of bolter-related literature	6
Development of solutions	6
Possible solutions	6
Criteria for ranking solutions	7
Protection of operator	7
Time	8
Cost	8
Discussion of solutions	8
Solution 1: Use interlock device to cut off power to controls when operator is out of position	8
Solution 2: Place fixed barriers at pinch points	9
Solution 3: Provide appropriate control guarding	9
Solution 4: Reduce fast-feed speed	10
Solution 5: Use automatic cutoff switches at pinch points	11
Solution 6: Redesign control bank to conform to accepted ergonomic principles	12
Solution 7: Use resin insertion tools and resin cartridge retainers	13
Extended-term solutions	14
Perform overall crewstation redesign	14
Reposition-redesign personal protective equipment	15
Reduce likelihood of drill steel jamming	15
Use automatic resin insertion devices	16
Recommendations	17
References	17
Appendix	18

ILLUSTRATIONS

1. Positioning deadman switch too close to fast-feed lever allows operator to activate both with one hand	9
2. Heavy steel tool tray welded onto HDDR bolter by mine personnel provides fixed barrier to mast pinch point	9
3. Unguarded controls are more likely to be activated by roof or rib falls	10
4. Average fast- and slow-feed speeds for roof bolters	10

ILLUSTRATIONS—Continued

5. Hydraulic safety bar installed on Fletcher HDDR roof bolter that acts as control guard and automatic cutoff switch	11
6. Knob shapes that can be recognized by touch by operators who wear gloves	12
7. Suggested knob shapes for roof bolters that relate to function being controlled	12
8. Two dual-boom bolter layouts illustrating mirror image and place arrangement of controls	13
9. Resin transfer tube designed by Birmingham Bolt	13
10. Resin insertion assist designed by Fletcher	14
11. Resin retaining devices: clip and parachute	14
12. USBM coiled cap lamp cord concept	15
13. Misalignment increases when boom goes from position 1 to position 2 unless roof bolter is moved forward	16

TABLES

1. Criteria used to search MSHA accident database	2
2. General information on mines visited to observe roof bolting	3
3. Categories and criteria used to evaluate proposed solutions	7
4. Solutions ranked using AHP	8
5. Effects of limiting fast-feed speed on roof bolters to two times slow-feed speed	11
6. Typical control movement stereotypes	13

UNIT OF MEASURE ABBREVIATIONS USED IN THIS REPORT

Metric Units

cm	centimeter
cm/s	centimeter per second
N	newton

U.S. Customary Units

in	inch
lbf	pound (force)

Human Factors Analysis of Roof Bolting Hazards in Underground Coal Mines

By Fred C. Turin and others¹

ABSTRACT

(Abstract here!) [X](#)

¹ Research Center, U.S. Bureau of Mines, [State (ie. PA. OR. MN.)]

INTRODUCTION

(Intro here!) X

REFERENCES

(enter here!) X